	5	Sanitized Copy Approved fo	and the state of t		P89B00569R000300	0160152-4	
				CEULII A	Comm	0 015	
	7. " - +	4 Sept 59	7 O P	SECR			
				e e estado de es	Same of the pri	y Ku	
25X1		DIRECTOR			er general er en er En er en er en en en er en	P	
	100						
	1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	DPD (1.2.3.4,5,6,7,8)			ROUTINE		
		s/c (9)		1100: 1882			
	TOR: 1602Z 4 SEPT 59		PT RO		`	IN Ø5725	
		The state of the s		1		25X1	
25X1					to constitution	25X1	
	••				*		
25X1		Kuritur Din					
25X1			OT RCVD				
	LOW FREQUENCY BEACON APPARENTLY IN GOOD SHAPE EXCEPT						
	FOR POWER SUPPLY. POWER NORMALLY OBTAINED FROM SKVA TRANSFORMER						
25X1		WITH GASOLINE DRIVEN GENERATOR AS BACKUP. BOTH PRESENTLY INOP.					
		WE LOANED BASE COMMO OFFICER 3.5 KVA ONAN GENERATOR AND HE PUT					
		OUT STRONG SIGNAL THIS AFTERWOON. FYI POWER TO IS 500 25X1					
		WATTS, NOT 5 AS WE BELIEVED. BELIEVE TRANSFORMER WILL BE REPLACED					
	IMMEDIATELY, HOWEVER WE WILL LEAVE OWAN AS EMERGENCY POWER UNTIL						
		PROBLEMS RESOLVED. FY I BOTH FLIGHTS LANDED WITHIN 10					
	MINUTES OF HEAVY THANDERSTORMS WITH STEADY RAIN CONTINUING UNTIL						
25X1		MIDNIGHT. BELIEV					
	AND C 130 FLIGHTS DURING PRESENT RAINY SEASON OR DURING NIGHT						
	OPERATOONS. WE WILL PROBABLY SOON HAVE PORTABLE BEACON AS						
	ADDITIONAL AID AND BACKUP PRESENT R						
	LOCALLY UNOBTAINABLE ITEMS FROM SUF						
	GOOD CHANCE NECESSARY ITEMS AVAILABLE IN GOOD CONDITION USAF SALVAGE YARDS. END OF MESSAGE						
			T O P4	SECRE		Men	
		25 YFA F	R RE-REVIEW		en e	e y de	
		20 12/11					